Material Safety Data Sheet

Emergency Phor 708-438-180

Section 1 Product Identification					
TRADE NAME DEARCIDE 706	PRODUCT	TYPE	CODE IDENT.		
DOT SHIPPING NAME Compound Industrial Pro					
Section 2 Hazardous Ingredients					
	· CAS NUMBER	%	EXPOSURE CRITERIA		
Alkyl trimethylene diamine	109-76-2	C 15	Not e tablish d		
Isopropyl alcohol	67-63-0	(2	TWA: 400 ppm		
Inert ingredients		C 83	Not establi hed		

HMIS 1-0-0	FPA REGISTRATION NO. 4643-10			
Section 3 Physical Data				
BOILING POINT, 760 mm Ha	ND	MELTING POINT	NA.	
FREEZING POINT	24 F	VAPOR PRESSURE	20 an Ha	
SPECIFIC GRAVITY (H20=1)	V 66 T	SOLUBILITY IN H20	Complete	
VAPOR DENSITY (AIR=1)	ND.	EVAPORATION RATE; (By Ac = 1)	(1	
% VOLATILES BY VOLUME APPEARANCE & ODOR	ND	На	8.2	
APPEARANCE & ODOR				

LASH POINT (& METHOD USED)	FLAMMABLE LIMITS IN AIR % BY VOLUME LOWER UPPER		AUTO IGNITION TEMPERATURE
None	ND	ND	CM
XTINGUISHING MEDIA: PECIAL FIRE FIGHTING PROCEDURES:	FOAM	CO2 DRY CHEM	ICAL
Firefighters should wear dependence of the firefighters apparatus.	full protective gear i	actuding self-co	ntained

Section 5 Reactivity Data					
STABILITY (NORMAL CONDITIONS)	CONDITIONS TO AVOID	teeneratur	AG		, eVene
INCOMPATIBILITY (MATERIALS TO AVOID)					
Strong oxidizing agents					
HAZARDOUS DECOMPOSITION PRODUCTS					
CC. CO2. mitragen oxides	611	- 179	50	T-Key	

GRACE Dearborn

Dearborn Division W. R. Grace & Co. - Conn., 300 Genesee Street, Lake Zurich, IL 60047 (708) 438-1800

Section 6 Health Hazard Information

TOXICITY INFORMATION:

No TLV established for product, see secti n 2 for comp nent inf reati n.

EFFECTS OF OVEREXPOSURE:

INHALATION:

Inhalation of mist may irritate respiratory passag s.

INGESTION:

May be harmful if swallowed.

SKIN OR EYE CONTACT: Irritating to skin on prolonged or repeated contact.

EMERGENCY AND FIRST AID PROCEDURES

INHALATION:

Remove affected persons to fresh air and treat symptoms.

INGESTION:

If conscious, dilute with milk, egg whites or large quantiti of water. Consult a physician.

SKIN CONTACT:

Wash affected area thoroughly with soap and water. contaminated clothing and wash before reuse.

EYE CONTACT:

Flush eyes with large amounts of water for 15 minutes.

medical attention

Section 7 Special Protection Information

VENTILATION REQUIREMENTS

Use adequate eschanical

RESPIRATORY PROTECTION (SPECIFY TYPE)

None special

GLOVES

Impervious

Goggles or face shield OTHER PROTECTIVE CLOTHING AND EQUIPMENT

Adequate protective clothing to minimize skin contact. Use good personal hugiens.

Section 8 Spill or Leak Procedures

STEPS TO TAKE IF MATERIAL IS RELEASED OR SPILLED

Vear protective clothing. Collect using absorbent, place in container for proper disposal.

WASTE DISPOSAL METHOD

Dispose of in accordance with EPA regulations, under FIFRA. contaminate water, food, or feed by storage or disposal. Do not

Section 9 Special Precautions

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Agitate before using, keep container closed when not in use.

OTHER PRECAUTIONS

FOR INDUSTRIAL USE ONLY. KEEP OUT OF REACH OF CHILDREN.

PREPARED BY: S. Morss

(10/26/89 DATE:

The data included herein are presented according to W. R. Grace & Co.'s practices current at the time of preparation verification of the original recipients hereof and do not constitute a representation or wormerly for which Grace assuremain currently informed on chemical hazard information, to design and update its own safety program and to contested; acceptational health, right to know and environmental protection. ords available solely for the consideration, investigation and onsibility. It is the responsibility of a recipient of this data to tional, federal, state, and local laws and regulations applicable

E Dearborn

Decriborn Division W. R. Grace & Co. - Conn., 300 Genesee Street, Lake Zurich, IL 60047 (708) 438-1800